

## PRODUCT CHANGE NOTIFICATION

Date: March 12<sup>th</sup>, 2012

PCN: PCN LEDIL025

Subject: Mechanical issue between BROOKE-SCR series and Citizen CLL030 LEDs.

Description: LEDiL found in mechanical inspection that solder pads of Citizen CLL030 LEDs are too close to emitting area and there is not enough space for BROOKE-SCR series of reflectors.

Time line: This Product Change Notification is valid immediately.

Part numbering: C12083\_BROOKE-SCR-M  
C12084\_BROOKE-SCR-W

Above part numbers have been discontinued from product selection of Citizen CLL030 with no replacement

Contact information: Sampsa Nurmi  
LEDIL Oy  
Salorankatu 10  
24240 SALO  
FINLAND  
sampsanurmi @ ledil.com