



PRODUCT CHANGE NOTIFICATION

Date: September 18, 2015
PCN: PCN LEDIL 109 a, b, c, d

Subject: PCN 109.a - Change of packaging quantities

Description: As part of our continuous improvement process regarding the logistics LEDiL has changed the packaging quantities of following products.

Time line: This change is valid immediately

Changes:

AFFECTED PRODUCT	Old BOX qty.	Upd. BOX qty.	Old MPQ	Upd. MPQ	Old MOQ	Upd. MOQ	Old Gr2	Upd. Gr2	Old Gr3	Upd. Gr3
F13185_GERI-RZ	224	288	32	32	96	96	224	288	10080	10080
F13671_ANGE-RZ-LENS	480	1250	60	60	60	60	60	60		
CP12583_LXB3-RS2	1680	1680	115	112	230	112	1680	1680	10080	10080
CP12668_LXB3-D	1680	1680	115	112	230	112	1680	1680	10080	10080
CP12669_LXB3-M	1680	1680	115	112	230	112	1680	1680	10080	10080
CP12670_LXB3-W	1680	1680	115	112	230	224	1680	1580	10080	10080
CP12846_LXB3-O-90	3680	1680	115	112	230	224	3680	1680	11040	10080

Contact information: Tero Mäkinen
LEDIL Oy
Salorankatu 10
24240 SALO, FINLAND
tero.makinen@ledil.com



PRODUCT CHANGE NOTIFICATION

Date: September 18, 2015
PCN: PCN LEDIL 109 a, b, c, d

Subject: PCN 109.b – Change of assembly instructions

Description: As part of our continuous improvement process regarding the quality of our products LEDiL has updated C13806_MIRELLA-XW-PF assembly instructions to include glue for fastening.

Time line: This change is valid immediately

Affected products: C13806_MIRELLA-XW-PF

Included in assemblies: CN14209_MIRELLA-XW-PF-VER013
CN14211_MIRELLA-XW-CL-PF-VER013
CN14212_MIRELLA-XW-DL-PF-VER013
CN14568_MIRELLA-XW-DL-PF
CN14572_MIRELLA-XW-CL-PF
CN14576_MIRELLA-XW-RZL-PF
CN14755_MIRELLA-XW-PF-XTM

Changes: C13806_MIRELLA-XW-PF assembly instructions has been updated to include glue for fastening. This change does not have effect on optical performance of the products.

Contact information: Tero Mäkinen
LEDIL Oy
Salorankatu 10
24240 SALO, FINLAND
tero.makinen@ledil.com



PRODUCT CHANGE NOTIFICATION

Date: September 18, 2015
PCN: PCN LEDIL 109 a, b, c, d

Subject: PCN 109.c - Change of product compatibility

Description: As part of our continuous improvement process regarding the quality of our products LEDiL has found F14170_FLORENCE-ZT25 to be mechanically incompatible with following shades.

Time line: This change is valid immediately

Affected products: F14170_FLORENCE-ZT25
C14453_FLORENCE-3R-SHD-GR
C14592_FLORENCE-3R-SHD-BLK
C14646_FLORENCE-3R-SHD-WHT

Changes: F14170_FLORENCE-ZT25 has been found to be mechanically incompatible with the shades listed and not recommended for designs.

Contact information: Tero Mäkinen
LEDIL Oy
Salorankatu 10
24240 SALO, FINLAND
tero.makinen@ledil.com



PRODUCT CHANGE NOTIFICATION

Date: September 18, 2015
PCN: PCN LEDIL 109 a, b, c, d

Subject: PCN 109.d – Discontinued products

Description: As part of our continuous improvement process regarding the quality of our products LEDiL has discontinued the manufacturing of FA11827_LM1-WW.

Time line: This change is valid immediately. Stock depleted.

Affected products: FA11827_LM1-WW

Changes: FA11827_LM1-WW manufacturing has been discontinued.

Contact information: Tero Mäkinen
LEDIL Oy
Salorankatu 10
24240 SALO, FINLAND
tero.makinen@ledil.com