



## PRODUCT CHANGE NOTIFICATION

Date: January 28, 2016  
PCN: PCN LEDIL 115 a, b, c

---

**Subject:** PCN 115 a - Change of packaging quantities

**Description:** As part of our continuous improvement process regarding the logistics LEDiL has changed the packaging quantities of following products.

**Time line:** This change is valid immediately

**Changes:**

AFFECTED PRODUCT	Old BOX qty.	Upd. BOX qty.	Old MPQ	Upd. MPQ	Old MOQ	Upd. MOQ	Old Gr2	Upd. Gr2	Old Gr3	Upd. Gr3
FN14828_OLIVIA-M	120	<b>140</b>	20	<b>20</b>	120	<b>140</b>	2000	<b>2100</b>	10000	<b>10080</b>
FN14637_OLIVIA-S	120	<b>140</b>	20	<b>20</b>	120	<b>140</b>	2000	<b>2100</b>	10000	<b>10080</b>
FN14976_STELLA-DWC2		<b>70</b>		<b>10</b>		<b>70</b>	2000	<b>2030</b>	10000	<b>10010</b>
CA12986_LXP2-O-90	2160	<b>2700</b>	144	<b>180</b>	228	<b>180</b>	1680	<b>2700</b>	10800	<b>10800</b>
CA14601_VERONICA-SQ-MINI-RS	5544	<b>5544</b>	252	<b>252</b>	252	<b>252</b>	5544	<b>5544</b>	11008	<b>11088</b>
CA14602_VERONICA-SQ-MINI-O	5544	<b>5544</b>	252	<b>252</b>	252	<b>252</b>	5544	<b>5544</b>	11008	<b>11088</b>

Contact information: Tero Mäkinen  
LEDIL Oy  
Salorankatu 10  
24240 SALO, FINLAND  
tero.makinen@ledil.com




**Subject:** PCN 115 b - Change to the flange of IP-2X6 modules

**Description:** As part of our continuous improvement process regarding the quality of our products LEDiL has changed the mechanical design of the flange on some of our STRADA-IP-2X6 and HB-IP-2X6 lenses. Changes improve durability of modules around screw towers and don't have other mechanical or any optical influences on the performance or use of the products.

**Affected products:**  
C14229\_HB-IP-2X6-WWW  
CS14263\_HB-IP-2X6-WWW  
C14017\_STRADA-IP-2X6-DWC-90  
CS14145\_STRADA-IP-2X6-DWC-90  
C12861\_STRADA-IP-2X6-DWC  
CS12862\_STRADA-IP-2X6-DWC

**Time line:** We will deplete existing stock before shipping new parts.

**Changes:**



**Contact information:** Tero Mäkinen  
LEDIL Oy  
Salorankatu 10  
24240 SALO, FINLAND  
tero.makinen@ledil.com



---

<b>Subject:</b>	<b>PCN 115 c - Change of material</b>
Description:	As part of our continuous improvement process regarding quality of our products LEDiL has changed silicone raw material grade used on our STELLA-family into harder grade. This change doesn't have any effects on the optical performance or UL ratings of products. Mechanical changes are limited to the change in shore hardness and doesn't change functionality of the products.
Affected products:	FN14074_STELLA-HB FN15186_STELLA-HB F14021_STELLA-HB F14514_STELLA-T4 FN14645_STELLA-T4 FN15187_STELLA-T4 F14627_STELLA-FRESNEL FN14720_STELLA-FRESNEL FN15188_STELLA-FRESNEL
Time line:	We will deplete existing stock before making changes
Changes:	Silicone raw material used for F14021_STELLA-HB, F14514_STELLA-T4 and F14627_STELLA-FRESNEL is changing into harder grade.
Contact information:	Tero Mäkinen LEDIL Oy Salorankatu 10 24240 SALO, FINLAND tero.makinen@ledil.com